


## SAMSUNG ML 1910/1915 - MLT-D1052

Investigation by Delacamp has shown that the ML-1910 series OEM cartridges have a PCR cleaning roller (see below) that wears out fast. This problem leads to insufficient PCR cleaning and in the end to bad printouts.



The Delacamp Wiper Blade ([Item number 30073](#)) with the PCR cleaning felt is an effective yet inexpensive solution.

