






Instruction Sheet of Delacamp HP9000 Mag Roller New Contact Plate and Delacamp HP9000

New Contact Plate for Old Style End Cap

HP9000 Mag Roller New Contact Plate	HP9000 New Contact Plate for Old Style End Cap
	

The Old Style Mag Roller Contact design in the HP9000 Cartridge can cause intermittence printing due to bad conductivity between the Mag Roller and the contact in the end cap. The new HP9000 has a revised design and New Style Mag Roller Contacts and End Cap Contact Plate to solve the problem. Delacamp has developed the HP9000 Mag Roller New Contact Plate and HP9000 New Style Contact Plate for converting the HP9000 Old Style End Cap to have the New Style Contact design.

Procedures

	<p><u>Step 1</u> Remove the Old Style OEM Contact Plate and the Contact Pin from the OEM HP9000 Old Style Right End Cap.</p>
	<p><u>Step 2</u> Assemble the Delacamp HP9000 New Contact Plate on the OEM HP9000 Right End Cap and clip into the location provided.</p>
	<p><u>Step 3</u> Assemble the Delacamp HP9000 Mag Roller New Contact Plate into the Mag Roller and add some conductive grease on the surface of the Delacamp HP9000 Mag Roller New Contact Plate. Reassemble end cap onto cartridge.</p>