







## Installation of the Reset Lever for Brother TN2000 Toner Cartridge

<b>Brother TN2000 Toner Cartridge (starter cartridge without Reset Lever)</b>	<b>TN2000 Mechanical Reset Lever</b>
 <p style="text-align: center; color: red;"><b>Slot for Reset Lever</b></p>	

### Installation Procedures

<p style="text-align: center;"><b><u>Step 1</u></b></p> 	<p>Unscrew and take off the Drive Train End Cap.</p>
<p style="text-align: center;"><b><u>Step 2</u></b></p>  	<ol style="list-style-type: none"><li>1.) Install the TN2000 Mechanical Reset Lever into the Drive Train End Cap.</li><li>2.) Rotate the Reset Lever to the specified position for printer to detect the Reset Lever.</li></ol>
<p style="text-align: center;"><b><u>Step 3</u></b></p> 	<ol style="list-style-type: none"><li>1.) Screw the Drive Train End Cap on the Toner Cartridge.</li><li>2.) Installation completed.</li></ol>